

EMBOSSING STAMPS UPPER AND LOWER PARTS

Group 1510


Machine embossing stamps

For raised sheet stamping, machine stamps with a depressed engraving (upper part) and a raised engraving (lower part) are required.

To engrave these stamps, we require information regarding the thickness of the sheets being stamped. The engraving and design are completed based on your instructions, mainly using the material 1.2080, ground on all sides.



embossing example



Subject to change. 05-14